

FIG. 1
CONVENTIONAL ART





FIG. 2
CONVENTIONAL ART



W1,W2,W3 = 000	---	$P_{ind} = 5\text{mw}$
= 001	---	$P_{ind} = 6\text{mw}$
= 010	---	$P_{ind} = 7\text{mw}$
= 011	---	$P_{ind} = 8\text{mw}$
= 100	---	$P_{ind} = 9\text{mw}$
= 101	---	$P_{ind} = 10\text{mw}$
= 110	---	$P_{ind} = 11\text{mw}$
= 111	---	$P_{ind} = 12\text{mw}$

FIG. 3
CONVENTIONAL ART




FIG. 4A
CONVENTIONAL ART




FIG. 4B
CONVENTIONAL ART




FIG. 5




FIG. 6




FIG. 7




FIG. 8A




FIG. 8B

